

Reasons Why Projects Might Not Get Approved in the STIP

Documentation

- 1 S/TIP supporting documentation has not been uploaded to eSTIP.
- 2 S/TIP *suggested* total funding exceeds *available* total funding.
- 3 MPO Resolution and/or TTC MO (e.g., rural, statewide programs) is not consistent with the TIP, S/TIP, UTP (rural) and/or Plan.
- 4 Public Involvement is not consistent with the TIP, S/TIP, UTP (rural) and/or Plan.

S/TIP to TIP

- 5 S/TIP project design concept or scope is inconsistent with the TIP project design concept or scope.
- 6 S/TIP phase of work (e.g., E, R, C or T) is inconsistent with the TIP phase of work.
- 7 S/TIP funding (e.g., total, YOE) is inconsistent with the TIP funding.

S/TIP to Plan (RTP, MTP)

- 8 S/TIP project design concept or scope is inconsistent with the current Plan project design concept or scope.
- 9 S/TIP project design concept or scope is consistent only with the future Plan project design concept or scope.
- 10 S/TIP funding is inconsistent with the Plan.

S/TIP Description of Work

- 11 Added capacity description does not include existing to future lanes. It should include e.g., Construct 4-lane highway to 6-lane highway.
- 12 Nonadded capacity description does not include what the widening entails. It should include e.g., Widening 2-lane roadway to add shoulders.
- 13 Not enough information is provided to determine eligibility for the category of funding requested.

Other

- 14 The location of a project cannot be discerned from the limits and description provided. If the project is on a city street, add the name of the project within the limits from; i.e., On Green Street, from FM 493 to SH 61.
- 15 The project is ineligible for the requested category of funding.
- 16 Federal funds are requested for a non-FFCS facility.